Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	86	motor with coil with (rotating) with push$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 09:49
L2	12	("2598481" | "2868287" | "2946902" | "3515972" | "3639135").PN. OR ("4107483"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/08/24 09:41
L3	7445	motor with coil with (rotating)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 09:49
L4	3234	motor near3 coil with (rotating)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:50
L5	10363	motor near3 coil same motor near3 rotat$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:50
L6	2711	motor near3 coil same motor near3 rotating	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:50
L7	30	switch.ti. and 6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:53
L8	22	switching.ti. and 6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:53

L9	21	8 not 7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:58
L10	90997	motor near rotation	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:58
L11	2958	spring with 10	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:58
L12	322	switch$4.ti,ab. and 11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:58
L13	321	12 not 1 not 8 not 9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 09:59
L14	319	13 not 7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/24 10:21
L15	0	(388/1).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 10:21
L16	0	(388/11).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 10:21

L17	0	(388/$2).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 10:21
L18	9112	"388"/$3.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 10:22
L19	0	"388"/$2.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 10:21
L20	2	"388"/$3.ccls. and "185"/$3.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 10:22
L21	4652	"388"/$3.ccls.	USPAT	OR	OFF	2005/08/24 10:22
L25	125717	motor.ti. and rotat$4.ti,ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 10:24
L26	649	25 and "388"/$3.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/24 10:25
S1	3701	(385/16,18,25).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/08/23 13:36
S2	3690	(385/16,18,25).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/03/28 13:21
S3	22	stow$4 and S2	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/03/28 13:22

S29	5	("20010033731" | "20020054748" | "5025346" | "6229640" | "6388359").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/03/28 17:22
S30	13	("3683167" | "4223217" | "4598715" | "4607160" | "4607161").PN. OR ("4738506"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/03/28 17:48
S31	34	("4189206" | "4220396" | "4325604" | "4886335" | "4911520" | "4938552" | "5035482" | "5056886" | "5098207" | "5110194" | "5175776" | "5239599").PN. OR ("5483608").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/03/28 18:30
S32	2613	(385/16).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/08/23 13:39
S33	700	385/17.ccls. not S32	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/23 13:45
S34	161	(optic$3 near3 switch$5) same spring same motor$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/23 16:05
S35	2	"5483608".pn. and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/08/23 16:41
S36	24789	motor with coil with (rotate or rotation or rotating)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/23 16:42
S37	9221	motor with coil with (rotating)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/23 16:42

S38	4009	motor.ti. and S37	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/23 16:42
S39	103	motor with coil with (rotating) with push$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/08/23 16:43